

VESSEL INFORMATION

Date of Survey 9/13/2011 File # 11PAP913
Client William J. Montgomery
Vessel Name Telegraphill Hail Port Hanover,NH
Hull No. (HIN) GND00647G879 Model Year 1979
L.O.A. 43' 3" Beam 14' 1" Draft 4' 2"
Propulsion Twin Six cylinder marine diesel inboards and Aux gen/set
Document/Reg 628898 Net Tons 16 Gross Tons 22
Notes Grand Banks Classic trawler/yacht, Singapore built
Estimated Value (US Dollars) as appraised \$145,000.US
Replacement Value (US Dollars) Over \$550,000.US
Surveyed At Shipyard Quarters
Marina D#22
Charlestown,Ma.
While Vessel Was a float only

HULL CONSTRUCTION DETAILS

Material FBG Thickness of Planking FBG
Framing Size & Material FBG w/bonded floors/stringers/bulkheads
Deck Beams Size & Material FBG
Decking teak/fbg Bottom FBG Keel FBG Skegs None
Stem Type Plumb Stern Type Semi elliptical
Bulkheads Five major Location thru out
Hull Ventilation good Bilge Ventilation good
Hatches Fwd/Aft Opening Ports Many Deck Hatches Two aft
Cockpit Type Raised Lazaretttes Fwd/aft/FB Seating FB/cabins
General Condition of Topsides good, White all
General Condition of Decking good, White w/Teakwood decks
General Condition of Bilges good all areas

MACHINERY SPACES & UNDERWATER MACHINERY

Shaft Size 2" Material bronze Zincs na
Prop. Size 24" Blades na Material bronze Condition na
Strut Material bronze Condition na Bearing na
Rudder Material bronze Condition na Zincs na
Engine Stuffing Box Bronze/FBG tubes
Engine Location mid bilges Fuel Type diesel each
Turbo/Natural Natural each Engine Alarm each
Single/Twin twin Make Lehman # Cyl's. 6 each Rated HP 120e
Port S.N. F2400100 Hours 1471 Trans. S.N. nl Make BW
Stbd. S.N. F0400100 Hours 1497 Trans. S.N. nl Ratio 2/1
Flame Arrest. na Cond. Eng. Mounts 4each Cond. good
Bilge Blower two Condition good
Exhaust Piping Pipe/Hoses Condition good Cooling System FWC
Bilge Pumps Three Located thru out
Pumps Working? good each Auto Switches? each

STEERING SYSTEMS

Description: Twin mechanical by builder
Emergency tiller

HEATING & AIR CONDITIONING

A.C. / Heater Make Cruisaire Model 2-12K BTU each
Location thru out
Condition not operated Galley Vents none
Opening Ports Many Leaks? not Hatches Two Leaks? not

ELECTRICAL SYSTEM

Gen. Make Onan Output 8KW Serial # A790388593
Hours 1574 Fuel diesel Cooling FWC
Batteries 3 Volts 12v Location 8D fwd engine room
Condition approved systems
Batt. Switch Located Helm Working? yes
Battery Charger Make/Model Quest Amps 40
Shore Power 2/110 Amps 2/30 # Outlets two Location fwd/aft
Vessel Wiring 110/12volts Condition good
Main Panel Type 90%breakers Location helm/panel Condition good

GALLEY

Appliance(s) Location Portside fwd mainsalon w/Quasar microwave and
Stove Type Princess 3 burner w/oven 110volt only
Propane Tank Location None Is Woodwork Protected? Vented
Tubing Type na Location na
Shut-Off Type switches Location in line Condition good all
Pressure Water yes Hot Water yes Tank Make/Model Raritan 12gallon
Condition of Tank, Plumbing, Wiring good, bronze sea cocks
Refrigerator Make & Model SubZero freezer/fridge units
Location galley Condition good all
Water Heater 12gallon Fuel eng/110v Location Port ER

TANKAGE SYSTEMS

Fuel
Fuel Type Diesel No. Four Capacity 600g Location mid/aft outbd
Shape Odd Material Steel Condition good each
Secured By chocked Bonded each Lines & Vents copper/hose
Overboard Overflow? yes Location sides
Shut-Off Valves on Tanks? yes Accessibility good
Water
Number Two Shape Odd Capacity 200g Location aft
Material SS Condition good each

SAFETY EQUIPMENT

Ring One Whistle One Bell One
Flares Four Flare Gun one # Rounds Four
PFD's Eight minimum
Bow SS Stern Teak/SS
Lifelines Teak/SS Gates Three
Handrails Teak/SS Ext. Pulpit Teak

FIRE FIGHTING EQUIPMENT

Portable

| <u>Location</u> | <u>Type</u> | <u>Charged?</u> | <u>Date</u> | <u>Comments</u> |
|-----------------|-------------|-----------------|-------------|-----------------|
| Mid galley | ABC3# | yes | 10 | good |
| Helm | BC3# | yes | 10 | good |
| each cabin | BC3# | each | 10 | good |
| | | | | |
| | | | | |

Fixed

Type None Location na
Charged? na Dated _____ Sniffer? na Make na
Bilge Temp. Alarm na Bilge Level Alarm na Engine Alarm each

GROUND TACKLE

Type CQR Size 35# Rode na Chain 200'est
Type 2Danf Size 22/35 Rode 250' Chain 20'min
Dock Lines misc lengths and fenders

MARINE SANITATION DEVICE

No. Two Manual/Electric GalleyMaid Thru-Hulls each
"Y" Valve each Holding Tank Poly Location Stbd ER

ELECTRONICS & SPECIALIZED EQUIPMENT

| | <u>Make</u> | <u>Model</u> | <u>Notes</u> |
|---------------------|--------------------|---------------------|---------------------|
| Compass | 2Danforth | 6"each | good each |
| VHF Radio Telephone | Icom | M59 | good |
| VHF Radio Telephone | Icom | M56 | good |
| Depth | 2 Auto | TriData | good each |
| Loran | | | |
| Radar | Furuno | 1830 | good |
| GPS | | | |
| Auto Pilot | Simrad | Ap26/AP25 | good each |
| SSB | | | |
| Knot Log | 2 Auto | TriData | good each |
| Wind Inst. | | | |
| Windlass | Ideal | Tigres | good |
| Hailers | Std | LH10 | good |
| Stereo | Sony | am/fm/cd | good |

RIGGING & SAILS

Masts One Rig Hoist Type alum Boom na Type alum
Standing Rigging SS 1x19 Running Rigging dacron
Deck Winches _____ Mfg. By _____
Mast Winches _____ Winch Handles = _____
Main Sails _____ Jibs _____
Mizzens _____ Genoas _____
Spinnakers _____ Sail Covers _____ Dodgers _____
Awnings _____ Spinnaker Poles _____

MISC. EQUIPMENT

Two shorepower cords and adpters, Teak/SS swim platform/ladders,SeaWatch TV antenna, dual Flybridge Bimini/bridge cover, washdown systems, 10'dinghy ser#WMPA1294C000 w/Honda 4S outboard #2004947, Glending syncrnizers, remote searchlight, three helm wiper/washers, U Line icemaker, Vizio FS/TV. This report does not include a complete vessel inventory.

This yacht appraisal for tax purposes only is privileged and confidential for William J. Montgomery.

This report is not intended as a survey of the vessel.
